



Conditions on southern and central berms  
September 1, 2017

Discrete areas of armor rock on berms were displaced, outside of waste footprint

Three layer geotextile/geomembrane protection in western cell is in place and no waste was exposed





Anchor trench  
along south berm  
of west cell.

Note that anchor  
trench was dug  
into earthen  
material in the  
berm (not into  
waste)



This photo is on the central berm, but it depicts how the fabric was installed over the berms – overlapping the three layer geotextile/geomembrane protection within the western cell





Placing armor rock  
type B/C recycled  
concrete over  
fabric in the  
maintenance area  
on the south berm  
of the west cell

06/24/2011